



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
VERNON ROAD	O/S 1	TR: Felling	Rooting into c/w, unable to work around without unacceptable damage to tree	Quercus robur	Plant in new flexipave pit o/s boundary between 1-3, (offset towards 1, same as felled tree)	Acer rubrum 'October Glory'